STAT

STAT

STAT

MA DYFRWAL HOF ON

MEMERANDON FOR: Deputy Director (Support)

SUBJECT

: Monthly Report - Status of CIA Headquarters Building Project as of 31 March 1968

1. Planning

a. Templating of the Project & space was completed and	
approved. Subsequently, thirty seditional work spaces were	
provided by relocation of itself contingest and	
beach-head. Electrical fixtures planned for this project and	
Will Support Staff, together with stock for future use, have	
been delivered. Fart-beight partitions are evallable on the	
site to complete the WE Support Staff area. Bravings were	
propared for the contractor to indicate the minimum air	
conditioning changes to accommodate and	
WH Support.	

- b. The requirements for the _____ group noving into 1717 H Street were studied and a layout was made end approved. Due to the urgamey in secommodating this component, existing telephone service, furniture layouts, and partitions were used with only minor modifications.
- c. A design was nade and drawings are being propared for the guard house to be located in the turnal entrance to the basement.
- d. Buildings menagement was supplied irraines indicating platforms to be built for OTR Classrooms.
- e. The Architect-Engineer proposals for resovation or relocation of the Birector's suite were received and comments forwarded to the ASE with request. For estimates as to time and cost of each proposal. Pre-move surveys were completed for the south portion of the building.
- f. Moving Plans: The final contract move is on schedule; however, delay in delivery of part-height partitions may necessitate the move of Tank Force there by FRS moving forces.

CIN DISTRIBUTE BRE ONLY

e de la companya de la co

2.	Work	Progress

a.	Heating,	Ventilating	and	Alt	Conditioning	(HYAC)
-----------	----------	-------------	-----	-----	--------------	--------

- (1) The believing of air distribution and the calibration of control instruments on the second through the seventh floors (excepting dual dust systems) have been inspected and pessed by Public Buildings Service as of 27 Narch 1962. This means that the contractor has belanced and calibrated in accordance with specifications but some design and operations problems remain.
- (2) The balancing and calibration of the hual duct systems with which all conference rooms throughout the building are conditioned will be started on the north side in early April.
- (3) These areas of the first and ground floors served from the south basement fan rooms have been balanced and calibrated but not inspected.
- (4) Balancing and calibration of the first floor COMMO area were never completed before the area was occupied and closed off. It is planned that ______ who has a COMMO clearance will do this.

(5) A preliminary punch list for electrical and machanical equipment in the south pentheuse, south basement fan room, and kitchen fan room has been formulated but not yet passed to the contractor. (A punch list for machine equipment may be an active document for several months or indefinitely if contraversy arises concerning "satisfactory" performance and guarantee periods.)

STAT

STAT

STAT

c. Commitmetion

- approximately 37 per cent complete. Described are approximately 37 per cent complete. Described af the contractor's office building has been empleted. Repair of the main steam line is in progress was is reproximately 30 per cent complete. It is estimated that the repair itself will not be finished until minimy with back-filling, paving and isstallation of eight (8) light poles to follow. This repair will necessitate the closing of the back road on 10 April, and it will remain closed notil completion of acceptance test.
- (2) huilding: 0.37 per cent of the contract was completed this mouth britising completion to 99.05 per cent. At the end of Merch there were 100 employeen on the job compared to 175 at the end of February. Change orders were approved this mouth in the account of 5427,300, bringing the total to \$1.482,365, and the total approved and pending to \$2,244,337. All of the south half of the building has been accepted by PTS with the exception of the basement, penthense and the space prompted by the Communications Division on the grant floor. The basement reception area will be accepted to April. The garage area is ready but use of it will be delayed until repair of the damaged entrance door and construction of the guard pour are completed. Hence defects and culscions resain to be accepted on all Floors of the south half.
- d. Cafeberia: The interior of the exterior is complete with the exception of the valuat handrall for the belongy stairway and the installation of drapes. The installation of the stainless steel faucia on the exterior of the roof writes in 25 per cent complete.
 - a. Presentie falses and traveyor systems
 - (1) The matic Tabe Tystem C has been inspected and is satisfactory except for some very minor edjustments. In Systems A and B, about half of the stations were cleaned and adjusted curing March. Mr. Rong, Chief of Installations for Lamera Corporation, has visited several times and is reported to have told his see to have Systems A and B ready for testing by 1 May. In plans to put two (2) more men on in early spril. However, previous experience indicates that

и,

	В

Approved For Release 2002/08/21 : CIA-RDP80B01676R003100170035-4

II I FGIB

Approved For Release 2002/08/21: CIA-RDP80B01676R003100170035-4

ON MASSANT RES UMIN

b. Continue liaison with ISt and contractors on layout end equipment revisions and problems in completing construction on schodule.

Director of Logistics

Distribution:

0 & 1 - Addressee

1 - Ea. Liaison Officer

1 - OGC

1 - BD

1 - OL File

1 - D/L Chrono 1 - BPS (Proj. Off.) retained 3 - BPS (1 retained)

ILLEGIB

ILLEGIB

OL/L (19 April 1962)

5

Oly market to Child

SUBJECT: (Optional)				
FROM: Director of Logistics 1C-50 Quarters Eye				NO. DATE 26 (P) 1962
TO: (Officer designation, room number, and building)	D	ATE	OFFICER'S	COMMENTS (Number each comment to show from w
Donaing	RECEIVED	FORWARDED	INITIALS	to whom. Draw a line across column after each comm
Mr 3E-24 Hq.			√	1
2. Ma				
ET-FILE				
4.				-
5.				_
6.				
7.				
8.				
9.				
10.				
11.				
12.				
13.				
14.				
15.				ا کا